

# Oil Field Environmental Incident Summary

**Incident:** 20160225184605 **Date/Time of Notice:** 02/25/2016 18:46

**Responsible Party:** STATOIL OIL & GAS LP

**Well Operator:** STATOIL OIL & GAS LP

**Well Name:** DAVID NELSON SWD 1

**Field Name:** EAST FORK

**Well File #:** 12090

**Date Incident:** 2/25/2016

**Time Incident:** 14:51

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 156

**Rng:** 100

**Sec:** 14

**Qtr:**

**Location Description:**

**Submitted By:** Derrick Dion

**Received By:**

**Contact Person:** Derrick Dion  
6300 BRIDGE POINT PKY, BLDG 2  
SUITE 500  
AUSTIN, TX 78730

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	1	Barrels	1	Barrels		

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

faulty/ Malfunctioning vent valve.

**Areal Extent:**

all contained and cleaned up.

***Potential Environmental Impacts:***

none

***Action Taken or Planned:***

Trailer was removed from service by trucking firm until valve is repaired or replaced.

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 2/26/2016    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Stockdill, Scott

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the incident summary, this spill remained on location. NDIC retains oversight.